

ASH GROVE CEMENT COMPANY



"WESTERN REGION"

April 8, 1994

Mr. Larry Vaughn
Puget Sound Air Pollution Control Agency
110 Union Street, Suite 500
Seattle, WA. 98119-3958

Dear Mr. Vaughn,

In response to your questions listed on the attached compliance status report:

1. The magnehelix near the main baghouse lower compartment doors are intended to measure blow back pressure during the cleaning cycle and would normally read "0". The actual operating pressures are monitored in the control room and at other measuring locations on the baghouse and main fan. These instruments are routinely checked for proper operation.
2. Dusting at the tailend of the Ball #1 feed belt is being reduced by keeping the inspection doors closed on the weigh feeders located above the belt. Doors that are left open reduce the capture velocities at the tail end of the belt. The dust collector has been examined and under goes routine maintenance to identify and correct any performance deficiencies.

If you should have any further questions, please call 623-5596.

Sincerely,

Gerald J. Brown
Manager, Safety and Environment

Copy: KJR
ESP

AGCS2M000660

PUGET SOUND AIR POLLUTION CONTROL AGENCY

110 Union Street, Suite 500, Seattle, Washington, 98101-2038
Fax 206-343-7522

Registration No. 11339

Case No. _____

COMPLIANCE STATUS REPORT

Date of Report March 29, 19 94 at 250pm m.

Source Name <u>Ash Grove Cement Co</u>	Responsible Person, Title <u>Gerald Brown - Plant Safety Engr</u>
Location <u>3801 E Marginal Wy So - Seattle. 98134</u>	

☐ No violations of PSAPCA's regulations were observed at the time of my inspection, with respect to the areas of the facility I inspected.

☒ During my inspection I noted the following deficiencies:

1) Magnetix on main Bayhouse - compartments
2-3-5-6-7-8-9+11 did not function - All indicated

"0"

2) conveyor to Ball Mill #1 was leaking some dust
inside the building.

Please submit a written report within ten (10) working days describing the necessary corrective action you have taken or propose to take, including a schedule, to address the above deficiencies.

AGCS2M000661

Issued by

[Signature]

Received by

[Signature]
Signing this is not an admission of guilt

PUGET SOUND AIR POLLUTION CONTROL AGENCY

110 Union Street, Suite 500, Seattle, Washington, 98101-2038
Fax 206-343-7522

Registration No. 11339

Case No. _____

COMPLIANCE STATUS REPORT

Date of Report March 29, 19 94 at 2:50pm.

Source Name <u>Ash Grove Cement Co</u>	Responsible Person, Title <u>Gerald Brown - Plant Safety</u> <u>Eng'r</u>
Location <u>3801 E Marginal Wy So - Seattle. 98134</u>	


☐ No violations of PSAPCA's regulations were observed at the time of my inspection, with respect to the areas of the facility I inspected.

☒ During my inspection I noted the following deficiencies:

- 1) Magnetix on main Baghouse - compartments
2-3-5-6-7-8-9+11 did not function - All indicated
"0"
- 2) Conveyor to Ball Mill #1 was leaking some dust
inside the building.

Please submit a written report within ten (10) working days describing the necessary corrective action you have taken or propose to take, including a schedule, to address the above deficiencies.

Issued by



Received by

Signing this is not an admission of guilt

